

FIG. 1




FIG. 2





FIG. 3



3/9

FIG. 4

22

Mg	G	Mg	G	Mg	G
Cy	Ye	Cy	Ye	Cy	Ye
Mg	G	Mg	G	Mg	G
Cy	Ye	Cy	Ye	Cy	Ye
Mg	G	Mg	G	Mg	G

FIG. 5




FIG. 6





FIG. 7



5/9

FIG. 8










FIG. 9

$\sigma = 0.5, n = 1, m = 1, \theta g = 45^\circ$

0	0	0	0	0
0	3	21	3	0
0	21	158	21	0
0	3	21	3	0
0	0	0	0	0

/254



$\sigma = 0.5, n = 3, m = 1, \theta g = 45^\circ$


0	0	0	0	0
0	5	0	0	0
0	0	247	0	0
0	0	0	5	0
0	0	0	0	0

/257

$\sigma = 0.7, n = 1, m = 1, \theta g = 45^\circ$

0	1	1	1	0
1	11	30	11	1
1	30	83	30	1
1	11	30	11	1
0	1	1	1	0

/259



$\sigma = 0.7, n = 3, m = 1, \theta g = 45^\circ$


0	0	0	0	0
0	26	1	0	0
0	1	199	1	0
0	0	1	26	0
0	0	0	0	0

/255

$\sigma = 0.8, n = 1, m = 1, \theta g = 45^\circ$

0	1	3	1	0
1	13	29	13	1
3	29	64	29	3
1	13	29	13	1
0	1	3	1	0

/252



$\sigma = 0.8, n = 3.5, m = 1, \theta g = 45^\circ$


0	0	0	0	0
0	37	1	0	0
0	1	177	1	0
0	0	1	37	0
0	0	0	0	0

/255

$\sigma = 0.9, n = 1, m = 1, \theta g = 45^\circ$

0	2	4	2	0
2	15	27	15	2
4	27	51	27	4
2	15	27	15	2
0	2	4	2	0

/251



$\sigma = 0.9, n = 4, m = 1.25, \theta g = 45^\circ$


0	0	0	0	0
0	28	1	0	0
0	1	195	1	0
0	0	1	28	0
0	0	0	0	0

/255

$\sigma = 1.0, n = 1, m = 1, \theta g = 45^\circ$

1	3	6	3	1
3	15	25	15	3
6	25	41	25	6
3	15	25	15	3
1	3	6	3	1

/253



$\sigma = 1.0, n = 4.5, m = 1.5, \theta g = 45^\circ$


0	0	0	0	0
0	22	1	0	0
0	1	209	1	0
0	0	1	22	0
0	0	0	0	0

/257

7/9


FIG. 10

90



0	0	0	0	0
0	28	1	0	0
0	1	195	1	0
0	0	1	28	0
0	0	0	0	0

FIG. 11



9/9

FIG. 12

